

#whdentalwerk
f @ in ▶
wh.com

User Maintenance
Lexa MN-111



Replace the door gasket
🛒 Ref. **F460535X**



Perform monthly maintenance

○ Cycles
📅 Months



Replace the HEPA filter
🛒 Ref. **W322400X**

lexa



Scan the QR code
with your mobile
phone for **FAQ**.





W&H Sterilization Srl.
Via Bolgara, 2
24060 Brusaporto (BG), Italy
t +39 035-66 63 000
f +39 035-50 96 988
office.sterilization@wh.com
wh.com